

SD/SDC Generating&welding dual-use alternators/generators

Model	Rated output		Rated voltage (V)	Rated current (A)	Welding voltage Under unload (V)	Welding current (A)	Continuous rate under laod (%)	Current adjustment range for welding (A)
	KW	KVA						
Single-phase 230 V 50Hz/1500r/min COSφ = 1.0								
SD-5	5	5	230	21.7	<80	160	40	70-200
SD-7.5	7.5	7.5	230	32.6	<80	200	40	80-240
SD-10	10	10	230	43.5	<80	230	40	100-300
SD-12	12	12		52.2	<80	300	40	140-320
Three-phase 400V 50Hz/1500r/min COSφ = 0.8								
SDC-5	5	6.3	400	9	<80	140	40	60-160
SDC-7.5	7.5	9.4	400	13.5	<80	180	40	70-200
SDC-10	10	12.5	400	18.1	<80	225	40	80-280
SDC-12	12	15	400	21.7	<80	280	40	100-300

WWW.DIENMAYMANHQUYEN.COM